

# Oil Field Environmental Incident Summary

**Incident:** 20151016202900

**Date/Time of Notice:** 10/16/2015 20:29

**Responsible Party:** Buckhorn Energy Services

**Well Operator:** BUCKHORN ENERGY SERVICES, LLC

**Well Name:** J. W. FISKETJON 1

**Field Name:** TOBACCO GARDEN

**Well File #:** 8681

**Date Incident:** 10/16/2015

**Time Incident:** 16:25

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 150

**Rng:** 99

**Sec:** 3

**Qtr:** SW NW

**Location Description:**

**Submitted By:** Nancy Roberts

**Received By:**

**Contact Person:** Nancy Roberts

5613 DTC PARKWAY SUITE 800

GREENWOOD VILLAGE, CO 80111-3036

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	18.5	Barrels	18.5	Barrels		
Other						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

Spill was all contained within berm and was immediately picked up. No risk

**Areal Extent:**

***Potential Environmental Impacts:***

All of spill was contained within berm area and was immediately picked up. No impact is expected.

***Action Taken or Planned:***

Spill was contained in bermed area around pump. Spill was immediately picked up by vacuum truck.

***Wastes Disposal Location:*** Recovered spill was taken to the Leiseth SWD.

***Agencies Involved:***

***Updates***

---

***Date:*** 10/19/2015 ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Crowdus, Kory

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

Release remained on location according to the report. NDIC retains oversight.